

75 AND ZT CLUB TECHNICAL INFORMATION DOCUMENT

Model: Rover 75 / MG ZT Saloon models

Ref: TID-007

Derivative: All Saloon

Date: 17/11/2005

Title: Saloon Rear Bumper Removal

Description: This document is intended as a guide to removing and replacing the rear bumper on Saloon models.

Action required: Please see detail below.

Detail:

1. Open boot compartment fully
2. Remove two scrivets securing bumper to body underneath bumper
3. Remove torx screws securing bumper to wheelarch liner
4. Remove five scrivet fixings securing bumper to body
5. Carefully lift and pull outwards on each side of the bumper to fully release from the side mountings and remove from car (recommended that the aid of an assistant is used for this part).
6. On vehicles with parking sensors release multiplug behind bumper to complete removal of the bumper from the vehicle.
7. Reassembly is the reverse of removal.



Disclaimer: This document is intended as a guide only. You assume all responsibility for any problems you may have resulting from these instructions. The 75 and ZT owners club and the author of this document shall not be held responsible for any damages, losses or injury caused by the use of this document.